

## **Phase Indicator**

MODEL

8031

- Phase Indicator with open phase checker
- Phase indicator designed to check the presence of open phase and also the phase sequence by rotating disk and lamps.
- Can check a wide range of 3-phase power source from 110V to 600V.





Standard Type

| Operational Voltage       | 110~600V AC                                  |
|---------------------------|--|
| Time limit for continuous | >500V: within 5 minutes                      |
| Frequency Response        | 40~200Hz(AC 110~200V), 40~400Hz(AC 200~600V) |
| Safety Standard           | IEC61010-1 CAT.III 600V Pollution Degree 2   |
| Withstand Voltage         | 2200V AC for 5 seconds                       |
| Dimensions                | 106(L) × 75(W) × 40(D)mm                     |
| Weight                    | 350g approx.                                 |
| Cord                      | 1.5m(R: red S: white T: blue)                |
| Accessories               | 9029(Carrying Case)<br>Instruction Manual    |